

CLASSIFIED MESSAGE

SECRET

ROUTING			
1	DD	4	Intell
2	"	5	RB
3	DD	6	

DATE 26 MAR 63 1930Z

TO : DIRECTOR

FROM : KWBAIL

ACTION: OSA (1-2-3-4-5-6-7-8-9-10)

INFO : S/C (11)

50X1

ROUTINE

IN 70264

TOR 26 MAR 63 2114Z

TO CRIMP

INFO ADIC CUPID CACTUS SPECTRE CITE BAIL 5995

50X1

IDEALIST

REF.

50X1

1. DESENSITIZED SPOTS IN FRAMES

50X1

AND TWO PRESSURE MARKS 1/8 INCH APART ON

50X1

FRAMES

APPEAR TO BE A FILM

50X1

DEFECT INTRODUCED DURING MANUFACTURE OF THE KWMARK-10.

DEFECT CONFINED TO APPROXIMATELY 25 FEET OF LENGTH AND

TWO INCHES IN FROM EDGE WITH PARTIAL LOSS OF IMAGE IN

THE DEFECT AREA.

2. RECOMMEND INSTALLATION OF EXTRACTOR ROLLER

ASSEMBLY ON HTA/2 TO RESOLVE WATER SPOT PROBLEM.

END OF MESSAGE

*OPCEN NOTE: THIS MSG NOT RELAYED CUPID SINCE THAT

STATION DEACTIVATED. BAIL ADVISED VIA SERVICE MSG.

DOCUMENT NO. 78
NO CHANGE IN CLASS. ☒
☐ DECLASSIFIED
CLASS. CHANGED TO: TS S C
NEXT REVIEW DATE: 22/1
AUTH: HR 70-2
DATE 1509 71 REVIEWER: 010955

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.